

Meagan Redfern

SDMS Document ID

#731

From: OCARS_Pro@uncc.org
Sent: Monday, September 12, 2005 8:17 AM
To: Meagan Redfern
Subject: UNCC EMLCFM 2005/09/12 #00010 B0146978-00B NORM NEW




1052014

EMLCFM 00010 UNCCb 09/12/05 08:16 AM B0146978-00B NORM NEW STRT LREQ

Ticket Nbr: B0146978-00B
Original Call Date: 09/12/05 Time: 08:16 AM Op: MRE
Locate By Date : 09/14/05 Time: 11:59 PM Meet: N Extended job: N
State: CO County: DENVER City:
Addr: 3421 Street: VINE ST
Grids: 03S068W26NE : : Legal: N
Lat/Long: 39.766394/-104.963086 39.766394/-104.961290
: 39.763816/-104.963086 39.763816/-104.961290
Type of Work: SOIL EXCAVATION Exp.: N
Boring: N
Location: LOC ENTIRE LOT*ACCESS OPEN*TO INCLUDE ALL CITY PROPERTY AND
: EASEMENTS*INDIVIDUAL STRUCTURE
Company : PROJECT RESOURCES INC. Type: OTHR
Caller : MEAGAN REDFERN Phone: (303)487-0377
Alt Cont: AMY JAMES Phone: (303)487-0377
Fax: Email: MREDFERN@PROJECTRESOURCESINC.COM
Done for: EPA/ARMY CORPS OF ENGINEERS
Remarks:

Members 360NT3 = 360 NETWORK-TOUCH AMERICA ATCT01 = AT&T
Members CMSND00= COMCAST - NORTH DENVER PCNDU0 = XCEL ENERGY-NORTH
DENVER
Members PSND14 = XCEL ENGY--APPT SCHEDULE QLNCND0= QWEST LOCAL
NETWORK
Members QLNCND1= QWEST LOCAL NETWORK WCG01 = WILTEL
COMMUNICATION
You are responsible for contacting any other utilities that are not
listed above
including the following tier 2 members not notified by the center:
DNVH20 DENVER WATER DEPT (303)628-6666
DNVPR1 DENVER PARKS & REC. (303)458-4839
DTEO01 DNVR TRAFFIC ENG OPERAT. (720)865-4001
WWMG01 WASTEWATER MGMT DIVISION (303)446-3744





Property Access Checklist

Property ID: 731	<input type="checkbox"/> WORK STARTED	ON: __/__/__
Property Address: 3421 Vine St.	<input type="checkbox"/> WORK COMPLETED	ON: __/__/__

Property Owner: Jerry Valentine - Harlan	Property Renter:
Mailing Address:	Home Phone:
	Fax:
	Cell/Pager:
Home Phone: 312-296-6936	Additional Information:
Fax:	
Cell/Pager:	

<input checked="" type="checkbox"/> Notification Letter	Sent: 6/14/05	By: Sampling Co.
<input checked="" type="checkbox"/> Access Agreement	Signed: 6/17/05	By: J. Valentine - Harlan
<input checked="" type="checkbox"/> Restoration Agreement	Signed: 6/17/05	By: J. Valentine - Harlan
<input type="checkbox"/> Topsoil Sampling (if applicable)	___/___/___	By:
<input type="checkbox"/> Disposal Sampling (if applicable)	___/___/___	By:
<input type="checkbox"/> Garden Sampling (if applicable)	___/___/___	By:
<input type="checkbox"/> Utility Clearance	Called: ___/___/___	By:
<input checked="" type="checkbox"/> Video/Photos (Before)	On: ___/___/___	By: Amy James map - J. Reyer
<input type="checkbox"/> Video/Photos (During)	On: ___/___/___	By:
<input type="checkbox"/> Video/Photos (After)	On: ___/___/___	By:
<input type="checkbox"/> Video/Photos (30-Day)	On: ___/___/___	By:
<input type="checkbox"/> Property Completion Agreement	Signed: ___/___/___	By:
<input type="checkbox"/> Final Report	Issued: ___/___/___	By:

Air Monitoring (as applicable)

<input type="checkbox"/> Community <input type="checkbox"/> Crew	On: ___/___/___	By:
Results:		
<input type="checkbox"/> Community <input type="checkbox"/> Crew	On: ___/___/___	By:
Results:		
<input type="checkbox"/> Community <input type="checkbox"/> Crew	On: ___/___/___	By:
Results:		



Project Resources Inc.

Restoration Agreement

The purpose of this agreement is to provide a mutual agreement as to conditions of property prior to remediation activities. This will also serve as decontamination for the purpose of assuring that restoration activities are completed to the satisfaction of the property owner and the United States Environmental Protection Agency (EPA).

Property ID:	731
Property Address:	3421 Vine St.
Owner:	Jerry Valentine - Harlan
Phone:	3) 296-6936

On the attached diagram(s) indicate area(s) to excavated and depth of excavation, location of all known utilities, subsurface features, surface structures and landscaping features, access location(s) to be used by contractor, and the direction of North. Indicate distances, depths, material types, etc. Indicate digital photos by referencing the photo-log number with an arrow indicating direction of view.

Items To Be Removed By Owner Before Start Of Remediation: (Use additional sheets as necessary)

The removal, storage, disposal, and/or return of these items is the Owner's responsibility.

Item:	Asbestos
Item:	
Item:	
Item:	
Item:	
Item:	
Item:	



Items To Be Removed By Contractor During Remediation And Not Replaced
(Use additional sheets as necessary)

Item:	Clothesline poles
Item:	Bricks underneath Vline
Item:	
Item:	
Item:	
Item:	
Item:	

Items To Be Removed By Contractor During Remediation And Replaced
(Use additional sheets as necessary)

Item:	Remove front fence for access.
Item:	Bricks underneath Vline
Item:	in backyard
Item:	
Item:	
Item:	
Item:	



Project Resources Inc.

Landscape Inventory
(Use additional sheets as necessary)

Item	Quantity	Unit	Description/Explanation
Total Area Of Property To Be Excavated	2046	Square Feet	
Number of trees > 2 inch trunk diameter	4		
Number of trees < 2 inch trunk diameter	0		
Number of Sprinkler Zones, Control Valves, Timers, Heads, etc. Attach a sketch of the sprinkler layout.	N/A		Zones: _____ Heads: _____ Control Valves: _____
Number of and total size of all gardens / flower beds. Attach a sketch of relative sizes and locations.	# Of Beds: 1 # Of Gardens: _____ _____		Ft ² Of Beds: 2 x 20 Ft ² Of Gardens: _____



Project Resources Inc.

Item	Quantity	Unit	Description/Explanation
<p>Agreed upon value of plant materials <u>not</u> to be replaced by contractor.</p> <p>Note this value will be used to issue a plant voucher to the property owner.</p>	<p>Total # Of Beds:</p> <p><u>1</u></p>	<p>\$</p>	<p>Total Ft² Of Beds To Be Replaced With Certificate:</p> <p><u>$2 \times 20 = 40 \times 2.5 = 100$</u></p>
<p>Agreed upon list of plant materials that will be replaced by contractor. Be very specific and detailed.</p> <p>Include a sketch of where each plant will be placed by the contractor.</p>	<p><u>N/A</u></p>	<p>Each</p>	<p>Only Use For Plants That Are Being Saved and Re-planted</p>
<p>Agreed upon area of property to be replaced with grass sod.</p> <p>Include a sketch of the area(s) to be replaced with grass sod.</p>	<p><u>1530</u></p>	<p>SF</p>	<p>Total Ft² Of Sod To Be Laid: <u>1530</u></p>
<p>Area of City or County property to be landscaped per their requirements.</p> <p>Include a sketch of the area (s)</p>	<p>Total Ft²:</p> <p><u>540</u></p>	<p>SF</p>	<p>Sod: <u>540</u></p> <p>Brown Mulch: <u>—</u></p> <p>Red Mulch: <u>—</u></p>
<p>Agreed upon area of property to be replaced with mulch.</p>	<p>Total Ft² Of Mulch:</p> <p><u>—</u></p>	<p>SF</p>	<p>Red: <u>—</u></p> <p>Brown: <u>—</u></p>



Project Resources Inc.

Item	Quantity	Unit	Description/Explanation
Agreed upon area to be replaced rock.	Total Ft ² Of Rock: <u>474</u>	SF	Large: <u>474</u> Medium: <u>—</u> Small (pea gravel): <u>—</u> Driveway Gravel: <u>—</u>
Agreed upon area to be replaced with no groundcover.	Total Ft ² With No Groundcover: <u>40</u>		

Additional Comments / Instructions:

20' X 2' Flower bed to be ~~per~~ voucher



Project Resources Inc.

Additional Comments / Instructions Continued:

☐ Check the box if Owner does not want PRI to document interior foundation walls and possible pre-existing damage. By checking this box PRI is not responsible for any damage done to the interior of house, including foundation cracks or fissures.

☒ I agree

☐ I do not agree

☒ I agree

☐ I do not agree

Owner's Signature

Date

Contractor's Signature

Date

Property Check-List

Yes/No

1. NO Sprinkler System?
2. NO Basement Photos? (*owner requested*)
3. N/A Photos of Water Meter?
4. yes All 3 Signatures?
5. yes Number of Trees?
6. \$100.00 Approximate Voucher Size? *20x20=40*
7. yes Are all trees and bushes clearly labeled on the map?
8. yes Clotheslines marked and is it removed or replaced?
9. yes House accessible for equipment?
10. yes Owner clear of everything they will need to remove?
11. yes Owner clear the dates when we call him are approximate?
12. ✓ A second walk through done on the property to double check the map by the individual who did the video/photos?



RESTORATION CHANGE ORDER VB/I-70

Property ID # 731

Property Address 3421 Vine St.

Owner Name Jerry Valentine - Harlan

Date _____

Comments

- 24x2 Section in rear of home change large rock to driveway gravel - 52x4 Section of large Rock to soil on side of house. -
- No tree in left front of yard - Tree stays on left side of home in city property. -
- No tree on right side of city property. -
- Dig left rear corner of home (flower bed)

Owner Signature _____


Contractor Signature _____



Project Resources Inc.

9-25-05

Jerry refused
excavation because
she wanted us to
survey her property
& the change order





Property Access Checklist

Property ID: <u>M31</u>	<input type="checkbox"/> WORK STARTED ON: <u> </u> / <u> </u> / <u> </u> <input type="checkbox"/> WORK COMPELTED ON: <u> </u> / <u> </u> / <u> </u>
Property Address: <u>3421 Vine St.</u>	

Property Owner: <u>Jerry Valentine - Harlan</u>	Property Renter:
Mailing Address:	Home Phone:
	Fax:
	Cell/Pager:
Home Phone: <u>3) 296-6936</u>	Additional Information:
Fax:	
Cell/Pager:	

<input checked="" type="checkbox"/> Notification Letter	Sent: <u>6/14/05</u>	By: <u>Sampling Co.</u>
<input checked="" type="checkbox"/> Access Agreement	Signed: <u>6/17/05</u>	By: <u>J. Valentine - Harlan</u>
<input checked="" type="checkbox"/> Restoration Agreement	Signed: <u>6/17/05</u>	By: <u>J. Valentine Harlan</u>
<input type="checkbox"/> Topsoil Sampling (if applicable)	<u> </u> / <u> </u> / <u> </u>	By:
<input type="checkbox"/> Disposal Sampling (if applicable)	<u> </u> / <u> </u> / <u> </u>	By:
<input type="checkbox"/> Garden Sampling (if applicable)	<u> </u> / <u> </u> / <u> </u>	By:
<input type="checkbox"/> Utility Clearance	Called: <u> </u> / <u> </u> / <u> </u>	By:
<input checked="" type="checkbox"/> Video/Photos (Before)	On: <u> </u> / <u> </u> / <u> </u>	By: <u>Amy James map - J. Reyer</u>
<input type="checkbox"/> Video/Photos (During)	On: <u> </u> / <u> </u> / <u> </u>	By:
<input type="checkbox"/> Video/Photos (After)	On: <u> </u> / <u> </u> / <u> </u>	By:
<input type="checkbox"/> Video/Photos (30-Day)	On: <u> </u> / <u> </u> / <u> </u>	By:
<input type="checkbox"/> Property Completion Agreement	Signed: <u> </u> / <u> </u> / <u> </u>	By:
<input type="checkbox"/> Final Report	Issued: <u> </u> / <u> </u> / <u> </u>	By:

Air Monitoring (as applicable)

<input type="checkbox"/> Community <input type="checkbox"/> Crew	On: <u> </u> / <u> </u> / <u> </u>	By:
Results:		
<input type="checkbox"/> Community <input type="checkbox"/> Crew	On: <u> </u> / <u> </u> / <u> </u>	By:
Results:		
<input type="checkbox"/> Community <input type="checkbox"/> Crew	On: <u> </u> / <u> </u> / <u> </u>	By:
Results:		



Project Resources Inc.

Restoration Agreement

The purpose of this agreement is to provide a mutual agreement as to conditions of property prior to remediation activities. This will also serve as decontamination for the purpose of assuring that restoration activities are completed to the satisfaction of the property owner and the United States Environmental Protection Agency (EPA).

Property ID:	731
Property Address:	3421 Vine St.
Owner:	Jerry Valentine - Harlan
Phone:	3) 296-6936

On the attached diagram(s) indicate area(s) to excavated and depth of excavation, location of all known utilities, subsurface features, surface structures and landscaping features, access location(s) to be used by contractor, and the direction of North. Indicate distances, depths, material types, etc. Indicate digital photos by referencing the photo-log number with an arrow indicating direction of view.

Items To Be Removed By Owner Before Start Of Remediation: (Use additional sheets as necessary)

The removal, storage, disposal, and/or return of these items is the Owner's responsibility.

Item:	Lauren's bike
Item:	
Item:	
Item:	
Item:	
Item:	
Item:	
Item:	



Project Resources Inc.

Items To Be Removed By Contractor During Remediation And Not Replaced
(Use additional sheets as necessary)

Item:	Clothesline poles
Item:	Burrs underneath Vine
Item:	
Item:	
Item:	
Item:	
Item:	

Items To Be Removed By Contractor During Remediation And Replaced
(Use additional sheets as necessary)

Item:	Remove front fence for access.
Item:	Burrs underneath Vine
Item:	in backyard
Item:	
Item:	
Item:	
Item:	



Landscape Inventory
(Use additional sheets as necessary)

Item	Quantity	Unit	Description/Explanation
Total Area Of Property To Be Excavated	2046	Square Feet	
Number of trees > 2 inch trunk diameter	4		
Number of trees < 2 inch trunk diameter	0		
Number of Sprinkler Zones, Control Valves, Timers, Heads, etc. Attach a sketch of the sprinkler layout.	N/A		Zones: _____ Heads: _____ Control Valves: _____
Number of and total size of all gardens / flower beds. Attach a sketch of relative sizes and locations.	# Of Beds: 1 # Of Gardens: 1		Ft ² Of Beds: 2 x 20 Ft ² Of Gardens: _____

Item	Quantity	Unit	Description/Explanation
<p>Agreed upon value of plant materials <u>not to be replaced</u> by contractor.</p> <p>Note this value will be used to issue a plant voucher to the property owner.</p>	<p>Total # Of Beds:</p> <p><u>1</u></p>	\$	<p>Total Ft² Of Beds To Be Replaced With Certificate:</p> <p><u>$2 \times 20 = 40 \times 2.5 = 100$</u></p>
<p>Agreed upon list of plant materials that will be replaced by contractor. Be very specific and detailed.</p> <p>Include a sketch of where each plant will be placed by the contractor.</p>	N/A	Each	Only Use For Plants That Are Being Saved and Re-planted
<p>Agreed upon area of property to be replaced with grass sod.</p> <p>Include a sketch of the area(s) to be replaced with grass sod.</p>	1530	SF	Total Ft ² Of Sod To Be Laid: <u>1530</u>
<p>Area of City or County property to be landscaped per their requirements.</p> <p>Include a sketch of the area (s)</p>	<p>Total Ft²:</p> <p><u>540</u></p>	SF	<p>Sod: <u>540</u></p> <p>Brown Mulch: <u>—</u></p> <p>Red Mulch: <u>—</u></p>
<p>Agreed upon area of property to be replaced with mulch.</p>	<p>Total Ft² Of Mulch:</p> <p><u>—</u></p>	SF	<p>Red: <u>—</u></p> <p>Brown: <u>—</u></p>



Project Resources Inc.

Item	Quantity	Unit	Description/Explanation
Agreed upon area to be replaced rock.	Total Ft ² Of Rock: <u>474</u>	SF	Large: <u>474</u> Medium: <u>—</u> Small (pea gravel): <u>—</u> Driveway Gravel: <u>—</u>
Agreed upon area to be replaced with no groundcover.	Total Ft ² With No Groundcover: <u>40</u>		

Additional Comments / Instructions:

20 X 2 flower bed to be ~~per~~ voucher



Project Resources Inc.

Additional Comments / Instructions Continued:

☐ Check the box if Owner does not want PRI to document interior foundation walls and possible pre-existing damage. By checking this box PRI is not responsible for any damage done to the interior of house, including foundation cracks or fissures.

☒ I agree

☐ I do not agree

☒ I agree

☐ I do not agree

Owner's Signature

Date

Contractor's Signature

Date

large rock

$$24 \times 2 = 48$$

$$10 \times 22 = 220$$

$$52 \times 4 = 208$$

$$\underline{476}$$

rod

$$22 \times 15 = 330$$

$$160 \times 2 = 120$$

$$20 \times 15 = 300$$

$$20 \times 12 = 240$$

$$36 \times 15 = 540$$

$$\underline{1530}$$

ail

$$20 \times 2 = 40$$

cily

$$36 \times 15 = 540$$

$$\underline{\text{TOTAL}} = 2046$$

Consent For Access To Property

RIGHT OF ENTRY TO PREMISES

Grantor (the property owner) consents to and authorizes the United States Environmental Protection Agency (EPA) or its authorized representatives, collectively the Grantee, to enter and perform certain environmental response activities upon the following described premises:

Owner's Name: <i>Jerry Valentine</i>	Phone:
Addresses of Properties covered by this Agreement:	Address: <i>3421 Vine Street</i>
	Address:
	Address:

PURPOSE OF RESPONSE ACTIVITIES

The EPA is requesting access to collect soil samples and remove soil that contains elevated concentrations of arsenic and/or lead and may pose a health hazard. The soil will be removed and the excavated area(s) will be replaced with clean materials and restored. This work is being performed under the Vasquez Boulevard/I-70 Superfund Site remediation program.

An EPA representative will contact the Grantor in-person to discuss the work to be performed. The Grantor will have an opportunity to review and approve the planned soil removal and restoration work before it begins. Once the work is finished, the Grantor will be asked to review the work and confirm that it is complete and meets with the Grantor's approval. Upon completion, the Grantor will receive written documentation from EPA that the property has been remediated.

ENVIRONMENTAL RESPONSE ACTIONS

By signing this Access Agreement, the Grantor is granting the EPA, its employees, contractors and subcontractors the right to enter the property, at all reasonable times and with prior notice, for the sole purpose of performing the work. This access shall remain in effect until the work has been satisfactorily completed. The Grantor also agrees to:

Consentimiento para el Acceso de la Propiedad

DERECHO A ENTRAR LA PROPIEDAD

El otorgante (dueño/a de la propiedad) le da permiso y autoriza la Agencia para la Protección del Medio Ambiente de los Estados Unidos (EPA) y/o a sus representantes autorizados (Cesionario) a entrar y a llevar a cabo algunas actividades ambientales en la propiedad a continuación:

Dueño/a de la Propiedad:	Número de Teléfono:
---------------------------------	----------------------------

Dirección de las Propiedades Cubiertas por este Acuerdo:	Dirección:
	Dirección:
	Dirección:

PROPÓSITO DE LAS ACTIVIDADES AMBIENTALES

La EPA solicita el acceso a tomar muestras de tierra y a remover la tierra en su propiedad que tiene concentraciones altas de arsénico y/o plomo que podrían ser peligrosos a su salud. La tierra será removida y el(las) área(s) excavada(s) serán reemplazadas con materiales limpios. Este trabajo estará realizado abajo del Vasquez Boulevard/I-70 Superfund Site programa de remediación.

Un representante de la EPA contactará al Otorgente personalmente para discutir el trabajo que se va a realizar en la propiedad del Otorgente. El Otorgente tendrá la oportunidad de examinar y sancionar el plan de removimiento de tierra y el trabajo de restoración antes de comenzar. Cuando el trabajo se termine, el Otorgente revisará el trabajo, confirmará su terminación y cumplirá con su aprobación. Después de la terminación del trabajo, el Otorgente recibirá un documento escrito por la EPA que indicará que la propiedad ha sido remediada.

ACCIONES DE LA ACTIVIDAD AMBIENTAL

Por su firma de este Acuerdo de Acceso, el Otorgente concede el EPA, sus empleos, contratadores y subcontratadores el derecho a entrar la propiedad, en tiempos razonables y sin noticia anterior, para el único propósito a realizar el trabajo aquí descrito. Este acceso debería persistir en efecto hasta que el trabajo haya sido terminado. El Otorgente también está de acuerdo con:

- Remove obstructions including boats, trailers, vehicles, playscape items, wood piles, dog houses, etc;
- Remove flower bulbs or plants that the Grantor or the Grantor's tenant may wish to save;
- Water and maintain replacement vegetation, including fertilizer application, as necessary subsequent to an initial watering period by EPA, unless watering is restricted by Denver Water Board;
- Abide by health and safety guidance provided by EPA;
- If the property is rented, assist EPA in obtaining tenant approval for access to the property to perform the work if EPA is unable to obtain such access; and
- Allow videotaping and/or photography of the property including exterior and interior areas of buildings.

AGREEMENT NOT TO INTERFERE

The Grantor agrees not to interfere or tamper with any of the activities or work done, or the equipment used to perform the activities, or to undertake any actions regarding the use of said property which would tend to endanger the health or welfare of the Grantees or the environment, or to allow others to use the property in such a manner.

Should you have any questions about this program, please contact the VB/I-70 Command Center at (303) 487-0377.

☒ I grant access to my properties

☐ I do not grant access to my properties


Signature _____ Date _____

Signature _____

Date _____

☐ I would like to be present during any sampling that is required.

☐ My property has a working sprinkler system that will need to be replaced.

- Remover obstrucciones, incluyendo botes, remolque, vehículos, juguetes de niños, montones de madera, casas de perros, etc.
- Remover bulbos de flores, u otras plantas que el Otorgante o inquilino del Otorgante quisiera guardar;
- Regar y mantener el reemplazo de vegetación, incluyendo la aplicación de fertilizante, subsecuente a la riega inicial por la EPA, a menos que el uso de agua esté restringido por la Junta de Agua de Denver.
- Seguir las recomendaciones de la guía de Salud y Seguridad de la EPA;
- Si la propiedad es rentada, asistir a la EPA a obtener la aprobación del inquilino para tener acceso a la propiedad dende se va a llevar a cabo el trabajo, si acaso la EPA no logra obtener acceso; y
- Permitir a hacer un video y/o tomar fotos de la propiedad, incluyendo el área exterior y interior del edificio.

ACUERDO A NO INTERFERIR

El Otorgante está de acuerdo a no interferir o meterse en cualquier actividad o trabajo hecho, o equipo que va a llevar a cabo las actividades en la propiedad, o arriesgar la salud o bienestar de los Cesionarios o el medio ambiente, o permitir otras personas a usar la propiedad en alguna manera.

Si tiene preguntas sobre este programa, por favor llame al centro de comando de VB/I-70 a (303) 487-0377.

☐ Si, yo permito acceso a mi propiedad.

☐ No permito acceso a mi propiedad.

Firma

Fecha

Firma

Fecha

☐ Me gustaría ser presente durante de cualquier colección de muestras.

☐ Mi propiedad tiene un sistema de regar plantas y sacate (sprinkler system).

PROPERTY INFORMATION

Property ID: 731
House Number: 3421
Street: VINE ST
Address: 3421 VINE ST
Unit:
ZIP Code: 80205
Neighborhood: COLE
Zone: R2

Find Record



DECISION CRITERIA

Target Property? Yes
Soil Sampled? Yes
Removal Required? Yes
Removal Complete?

SOIL SAMPLE RESULTS

Phase 3A
Arsenic Decision Value 297
Lead Decision Value 250

OWNER INFORMATION

Owner Name: JERRY VALENTINE-HARLAN
Mailing Address: 3421 VINE ST
Mailing City State Zip: DENVER CO 80205

OTHER SAMPLE RESULTS

Media Description
Arsenic
Lead

Real Property Records

Date last updated: Friday, May 13, 2005

Real Property Search

If you have a question about the value, ownership, or characteristics of this property,
or any other property in Denver, please call the Assessor at 720-913-4162.

[View Map/Historic District Listing for this Property](#)

[Link to property tax information for this property](#)

[Link to property sales information for this neighborhood](#)

[Link to property sales information for all Denver neighborhoods](#)

PROPERTY INFORMATION

Property
Type: Residential

Parcel: 0226114013000

Name and Address Information

Legal Description

VALENTINE-HARLAN,JERRY

L 21 & N1/2 OF L 20 BLK
17

3421 VINE ST

CHEESMAN &
MOFFATS ADD
RESIDENTIAL

DENVER, CO 80205

Property Address:

Tax District

3421 VINE ST

DENV

Assessment Information

	Actual	Assessed	Exempt	Taxable
Current Year				
Land	32800	2610		
Improvements	183000	14570		
Total	215800	17180	0	17180
Prior Year				

Land	23500	1870		
Improvements	194700	15500		
Total	218200	17370	0	17370

Style: One Story

Reception No.: 0000010893

Year Built: 1926

Recording
Date: 01/23/98

Building Sqr. Foot: 1,277

Document Special
Type: Warranty

Bedrooms: 2

Sale Price: 10

Baths Full/Half: 1/1

Mill Levy: 64.402

Basement/Finished: 1277/1200

Lot Size: 4,690

Zoning: R2



3458

3444

3400
APPRX

3430

3426

3420

3404

3455

3451

3445

3439

3431

3427

3421

3415

3411

3401

TARGET SHEET
EPA REGION VIII
SUPERFUND DOCUMENT MANAGEMENT SYSTEM

DOCUMENT NUMBER: 1052014

SITE NAME: VASQUEZ BOULEVARD AND I-70

DOCUMENT DATE: 09/25/2005

DOCUMENT NOT SCANNED

Due to one of the following reasons:

- ☐ PHOTOGRAPHS
- ☐ 3-DIMENSIONAL
- ☐ OVERSIZED
- ☒ AUDIO/VISUAL
- ☐ PERMANENTLY BOUND DOCUMENTS
- ☐ POOR LEGIBILITY
- ☐ OTHER
- ☐ NOT AVAILABLE
- ☐ TYPES OF DOCUMENTS NOT TO BE SCANNED
(Data Packages, Data Validation, Sampling Data, CBI, Chain of Custody)

DOCUMENT DESCRIPTION:

3 - DVDs OF PROPERTY VIDEO, PROPERTY #731

